



## WINDROW TURNER MODEL RP-2 PARTS LIST

Item	Part No.	Description	Qty.
1	AS_0011305	3-Point Frame	1
2	AS_001447	Sliding Arm	1
3	AS_001446	Wheel Arm	1
4	GM_001008	Wheel Assembly, RH	2
5	CV_001350	Carriage Bolt, M10x1.5x25, GR4.6	40
6	SM_001096	Tine Plate	20
7	CZ_001159	Tine	80
8	SS_003019	Rim	2
9	SM_001095	Flange	2
10	CD_001004	High Hex Nut, M10x1.5	40
12	CZ_001141	Seal	2
13	CC_001019	Inner Bearing	2
14	CZ_001141	Wheel Hub	2
15	CC_001020	Outer Bearing	2
16	CD_001127	Low Hex Castle Nut, M18x1.5	2
17	CV_001427	Cotter Pin, M3.2x32	2
18	CZ_001176	Hup Cap	2
19	CZ_001141	Hub & Spindle Assembly	2
20	CV_001009	Hex Capscrew, M10x1.5x25, GR8.8	12
21	CD_001004	High Hex Nut, M10x1.5	12
22	AS_001048	Frame Pin	1
23	CV_001572	Hairpin Cotter, M3	1
24	CZ_001037	Hairpin	2
25	CV_001105	Hex Capscrew, M16x1.5x100, GR8.8	1
26	CG_001044	Lockwasher, M16	1
27	CD_001007	High Hex Nut, M16	1